Work Order (Bid Form)

WORK ORDER INFORMATION

Work Order Name: WO/12012NW4052/1

Work Order Type: Weatherization

Audit Name: Audit-12012NW4052

CLIENT INFORMATION

Client Name: 12012NW4052 Address:

38242 Client ID: 12012NW4052

Alt. Client ID: Henry

CLIENT CONTACT INFORMATION

12012NW4052 Applicant/Person of **~**

Record

AGENCY INFORMATION

Agency: Northwest TN EDC Agency Phone: (731) 364-3228

Address: 231 S. Wilson Street Fax:

> Dresden, TN 38225 **Email Address:**

Agency Contact: Radford, Randy Work Phone: (615) 686-3245

Cell Phone: (615) 335-7428

Email Address: Randy@energyhoundz.com

| Company Name & License Number: | |
|--------------------------------|--|
| Contractor's Signature: | |

COMMENT

Contractor to follow the Southeast Field Guide as applicable.

Client Name: 12012NW 4052 Client ID: 12012NW4052 Alt. Client ID: Henry

Work Order (Bid Form)

DOE Weatherization Assistant Work Order Name: WO/12012NW4052/1 Version 8.6.0 Report Run On: 5/24/2010 Page 1 of 10

| / | | d Frame and Install Atti or with 3/4" Plywood and ch | | | Componen | ts | | | Inspected |
|-------------|---|--|------------|----------------|--------------|------------|-------|---------------------|-----------|
| C | | Latches to Secure Door pprox. 10 sq. ft. | and Glue | Insulat | ion on Top o | of Attic A | ccess | | |
| | | | | | Estimated | <u> </u> | | Actual | |
| # | <i>Material / Labor</i> Labor | Description / Comment | Units | Qty | Unit Cost | Total | Qty | Unit Cost | Total |
| 10 | Unspecified | Misc Material | Each | 1 | | | | | |
| 0 | ther Detail | | | | | | 7 | 1 | |
| L | | | | | | | | | |
| | | | | | | | | | |
| | | | | Measur | e Sub Total: | | | Sub Total: | |
| | Field Notes: Measure 2 Ren | nove Rotten Decking in | Front Lef | t | Componen | ts | | | Inspected |
| // | Measure 2 Ren Cor | nove Rotten Decking in ner of Roof (approx. 128 est practices, reroof area | 8 sq. ft.) | t | Componen | ts | | | Inspected |
| II Co | Measure 2 Ren Cor omment Using b | ner of Roof (approx. 128 est practices, reroof area | 8 sq. ft.) | | Estimated | | | Actual | |
| // Cd | Measure 2 Ren Cor omment Using b Material / Labor | ner of Roof (approx. 128 | 8 sq. ft.) | Qty | | | Qty | Actual Unit Cost | |
| // Cd | Measure 2 Ren Cor omment Using b | ner of Roof (approx. 128 est practices, reroof area | 8 sq. ft.) | | Estimated | 1 | Qty | | |
| // Cc # 1 | Measure 2 Ren Cor omment Using b Material / Labor | ner of Roof (approx. 128 est practices, reroof area | 8 sq. ft.) | Qty | Estimated | 1 | Qty | | |
| # 1 2 | Measure 2 Ren Cor omment Using b Material / Labor Labor | ner of Roof (approx. 128 est practices, reroof area | 8 sq. ft.) | Qty 1 | Estimated | 1 | Qty | | |
| # 1 2 | Measure 2 Ren Cor omment Using b Material / Labor Labor Miscellaneous Su | ner of Roof (approx. 128 est practices, reroof area | 8 sq. ft.) | Qty 1 | Estimated | 1 | Qty | | |
| # 1 2 | Measure 2 Ren Cor omment Using b Material / Labor Labor Miscellaneous Su | ner of Roof (approx. 128 est practices, reroof area | 8 sq. ft.) | Qty 1 | Estimated | 1 | Qty | | |
| // Cc # 1 2 | Measure 2 Ren Cor omment Using b Material / Labor Labor Miscellaneous Su | ner of Roof (approx. 128 est practices, reroof area | Units | Qty 1 1 | Estimated | 1 | | | Inspected |

Report Run On: 5/24/2010 Page 2 of 10

| Material / Labor Description / Comment Units Qty Labor 1 Doors 1 Other Detail Measure 4 Replace Lockable Latch and Install Dead Bolt on Back Door DR2 | Estimate Unit Cost ure Sub Total: | d Total | Qty | Actual Unit Cost | Total |
|--|-------------------------------------|---------|-----|------------------|-----------|
| Labor 1 Doors 1 Other Detail Meas Field Notes: Measure 4 Replace Lockable Latch and Install | ure Sub Total: | | | Unit Cost | Total |
| Labor 1 Doors 1 Other Detail Meas Field Notes: Measure 4 Replace Lockable Latch and Install | ure Sub Total: | Total | | Sub Total: | Total |
| Doors 1 Other Detail Meas Field Notes: Measure 4 Replace Lockable Latch and Install | | | | | |
| Measure 4 Replace Lockable Latch and Install | | | | | |
| Measure 4 Replace Lockable Latch and Install | | | | | |
| Meas Weasure 4 Replace Lockable Latch and Install | | | | | |
| Field Notes: Measure 4 Replace Lockable Latch and Install | | | | | |
| Field Notes: Measure 4 Replace Lockable Latch and Install | | | | | |
| Field Notes: Measure 4 Replace Lockable Latch and Install | | | | | |
| Measure 4 Replace Lockable Latch and Install | Compone | | | | |
| omment | Estimate | | | Actual | Inspected |
| Material / Labor Description / Comment Units Qty | Unit Cost | Total | Qty | Unit Cost | Total |
| Labor 1 | | | | | |
| Miscellaneous Su 1 | | | | | |
| Other Detail | | | | | |
| | | | | | |
| | | | | | |
| Meas | ure Sub Total: | | | Sub Total: | |
| Field Notes: | | | | | |
| | | | | | |

| Measure 5 | - | ce Storm Window Inse ox. 26 x 18) | ert in WD | 9 | Component | ts | | I | nspected |
|----------------------------|-----------------------|--------------------------------------|------------|-----------------|------------------------------|----------|----------|------------------|--------------|
| | esponsil torm inse | oility of contractor to ver ert. | ify measu | ıremen | ts in the field | d before | ordering | g | |
| | | | | | Estimated | | | Actual | |
| # Material / La | abor | Description / Comment | Units | Qty | Unit Cost | Total | Qty | Unit Cost | Total |
| 1 Labor | | | | 1 | | | | | |
| 2 Windows | | | | 1 | | | | | |
| Other Detail | | | | | | | | | |
| | | | | | | | | | |
| | | | | | | | | | |
| | | | Į. | Measur | e Sub Total: | | | Sub Total: | |
| Measure 6 Comment S | = | ce Stove s not currently work and | d needs re | | Component g Estimated | | | | nspected |
| # Material/La | abor | Description / Comment | Unito | | | | | Actual | |
| 1 Labor | | | Units | Qty | Unit Cost | Total | Qty | Actual Unit Cost | Total |
| | | Coon, paon, Commons | Units | Qty 1 | Unit Cost | Total | Qty | | Total |
| 2 Miscellaneo | ous Su | | Onns | | Unit Cost | Total | Qty | | Total |
| 2 Miscellaneo | ous Su | | Omits | 1 | Unit Cost | Total | Qty | | Total |
| 2 Miscellaned Other Detail | ous Su | | Omits | 1 | Unit Cost | Total | Qty | | Total |
| | ous Su | | | 1 | Unit Cost | Total | Qty | | Total |
| | ous Su | | | 1 | Unit Cost | Total | | | Total |
| | | | | 1 | | Total | | Unit Cost | Total |
| Other Detail | | | | 1 | | Total | | Unit Cost | Total |

Report Run On: 5/24/2010

| | | place Window Sill on WD 08, WD9 | 6, WD7, | | Componen | ts | | ı | Inspected |
|--------------------|---|--|----------------------------|---------|---------------------|----------|---------|--------------------|-----------|
| C | omment Air sea | l after installing and paint t | o approxi | mate r | natch. | | | | |
| | | | | | Estimated | 1 | | Actual | |
| # | Material / Labor | Description / Comment | Units | Qty | Unit Cost | Total | Qty | Unit Cost | Total |
| 1 | Labor | | | 1 | | | | | |
| 2 | Windows | | | 1 | | | | | |
| c | Other Detail | | | | | | | | |
| | | | | | | | | | |
| | | | | | | | | | |
| | | | | Measur | e Sub Total: | | | Sub Total: | |
| | | | | | | | | | |
| | omment Respon | place Window WD10 nsibility of contractor to ver | ify measu | | Componen | | orderin | | Inspected |
| | | nsibility of contractor to ver | ify measu | | - | d before | orderin | | Inspected |
| C | omment Respon | nsibility of contractor to ver | ify measu <i>Unit</i> s | | nts in the fiel | d before | orderin | g | Inspected |
| <i>C</i> | omment Responding Window | nsibility of contractor to ver | | ıremer | ts in the fiel | d before | | g <i>Actual</i> | |
| C # | omment Responding Window Material / Labor | nsibility of contractor to ver | | Qty | ts in the fiel | d before | | g <i>Actual</i> | |
| C # 1 | omment Responding Window Material / Labor Labor | nsibility of contractor to ver | | Qty 1 | ts in the fiel | d before | | g <i>Actual</i> | |
| # 1 2 | omment Responsively Material / Labor Labor Windows | nsibility of contractor to ver | | Qty 1 | ts in the fiel | d before | | g <i>Actual</i> | |
| # 1 2 | omment Responsively Material / Labor Labor Windows | nsibility of contractor to ver | Units | Qty 1 1 | Estimated Unit Cost | d before | Qty | Actual Unit Cost | |
| # 1 2 | omment Responsively Material / Labor Labor Windows | nsibility of contractor to ver | Units | Qty 1 1 | ts in the fiel | d before | Qty | g <i>Actual</i> | Total |

Report Run On: 5/24/2010

| Measure 9 Rep | lace Window WD12 | | | Component | ts | | I | Inspecte |
|--|-------------------------------|----------------------|----------------|------------------------------------|----------|---------|---------------------|----------|
| Comment Respon window. | sibility of contractor to ver | rify measu | ıremer | its in the fiel | d before | orderin | g | |
| | | | | Estimated | <u>'</u> | | Actual | |
| Material / Labor | Description / Comment | Units | Qty | Unit Cost | Total | Qty | Unit Cost | Total |
| Labor | | | 1 | | | | | |
| Windows | | | 1 | | | | | |
| | | | ' | | | | | |
| Other Detail | | | | | | | | |
| | | | | | |] [] | | |
| | | | Moasur | e Sub Total: | |] | Sub Total: | |
| | | | Micasai | c oub rotur. | |] | | |
| Field Notes: | otherstrip Around All Do | ors | | Componen | ts. | | | Inspecte |
| Measure 10 Wea | ntherstrip Around All Do | ors | | Componen | | | | Inspecte |
| | | ors <i>Unit</i> s | | Componen Estimated Unit Cost | | Qty | Actual Unit Cost | Inspecte |
| Measure 10 Wea Comment Material / Labor | ntherstrip Around All Do | | Qty 1 | Estimated | 1 | Qty | Actual | |
| Measure 10 Wea Comment Material / Labor Labor | | | Qty | Estimated | 1 | Qty | Actual | |
| Measure 10 Weacomment Material / Labor Labor Doors | | | Qty 1 | Estimated | 1 | Qty | Actual | |
| Measure 10 Weacomment Material / Labor Labor Doors | | | Qty 1 | Estimated | 1 | Qty | Actual | |
| Measure 10 Weacomment Material / Labor Labor Doors | | | Qty 1 | Estimated | 1 | Qty | Actual | |
| Measure 10 Wea | | Units | Qty 1 1 | Estimated | 1 | | Actual | |

| _ | | | | | | | | | |
|---------------------------------|--|---|--------------------|----------------|-----------------------|----------|------|------------------|-----------|
| Commen | -Air Seal -Air Seal -Air Seal -Air Seal | Around Windows Trim Around Doors Attic Access Around Window A/C above door opening to top of crown molding in | | | rox. 70 ft.) | | | | |
| | | | | | Estimated | <u> </u> | | Actual | |
| # Material | / Labor | Description / Comment | Units | Qty | Unit Cost | Total | Qty | Unit Cost | Total |
| Labor | | | | | | | | | |
| 0 Miscella | aneous Su | Infiltration Reduction | Each | 1 | | | | | |
| Other Deta | ail | | | | | |] [| | |
| | | | | | | | | | |
| | | | | 14 | e Sub Total: | |] [] | Sub Total: | |
| | | | | weasur | e Sub Total: | | | oub rotar. | |
| | e 12 Fill C | Coulty | | | | | | | |
| | | d area is approx. 160 so area is approx. 846 sq. f | | | Componen | ts A1 | | | Inspected |
| | | d area is approx. 160 sq | | | Componen Estimated | | | Actual | Inspected |
| # Material | Floored | d area is approx. 160 sq | | Qty | | | Qty | | Inspected |
| # <i>Material</i> Labor | Floored | d area is approx. 160 so area is approx. 846 sq. f | t. | | Estimated | <u> </u> | Qty | Actual | |
| | Floored / Labor | d area is approx. 160 so area is approx. 846 sq. f | t. | | Estimated | <u> </u> | Qty | Actual | |
| Labor | Floored / Labor | d area is approx. 160 so area is approx. 846 sq. f Description / Comment Attic Insulation - Blown | t. <i>Units</i> | Qty | Estimated | <u> </u> | Qty | Actual | |
| Labor 1 Insulation | Floored / Labor | d area is approx. 160 so area is approx. 846 sq. f Description / Comment Attic Insulation - Blown | t. <i>Units</i> | Qty | Estimated | <u> </u> | Qty | Actual | |
| Labor 1 Insulation | Floored / Labor | d area is approx. 160 so area is approx. 846 sq. f Description / Comment Attic Insulation - Blown | Units SqFt | Qty 160 | Estimated Unit Cost | <u> </u> | | Actual | |
| Labor 1 Insulation Other Deta | Floored / Labor on | d area is approx. 160 so area is approx. 846 sq. f Description / Comment Attic Insulation - Blown | Units SqFt | Qty 160 | Estimated | <u> </u> | | Actual Unit Cost | |
| Labor 1 Insulation | Floored / Labor on | d area is approx. 160 so area is approx. 846 sq. f Description / Comment Attic Insulation - Blown | Units SqFt | Qty 160 | Estimated Unit Cost | <u> </u> | | Actual Unit Cost | |
| Labor 1 Insulation Other Deta | Floored / Labor on | d area is approx. 160 so area is approx. 846 sq. f Description / Comment Attic Insulation - Blown | Units SqFt | Qty 160 | Estimated Unit Cost | <u> </u> | | Actual Unit Cost | |

Client Name: 12012NW4052 Client ID: 12012NW4052 Alt. Client ID: Henry Work Order (Bid Form)
Work Order Name: WO/12012NW4052/1

DOE Weatherization Assistant Version 8.6.0 Page 7 of 10

Report Run On: 5/24/2010

| | Measure 13 DWH | Tank Insulation | | | Componen | ts | | | Inspected |
|--------------------|---|---|----------------------|--------------|---------------------|----------|-----|------------------|-----------|
| C | omment | | | | | | | | |
| | | | | | Estimated | <u> </u> | | Actual | |
| # | Material / Labor | Description / Comment | Units | Qty | Unit Cost | Total | Qty | Unit Cost | Total |
| 1 | Hot Water Equipm | DHW Tank Insulation | Each | 1 | | | | | |
| 2 | Labor | DHW Tank Insulation | Each | 1 | | | | | |
| 3 | Other | DHW Tank Insulation | Each | 1 | | | | | |
| C | Other Detail | | | | | | | | |
| | | | | | | | | | |
| | | | | | | | | | |
| | | | | Measur | e Sub Total: | | | Sub Total: | |
| | Manager 44 DWI | Dina Inquiation | | | <u></u> | 40 | | | Inspector |
| | Measure 14 DWH omment | Pipe Insulation | | | Componen | | | | Inspected |
| С | omment | | | | Estimated | 1 | | Actual | |
| C # | omment Material / Labor | Description / Comment | Units Fach | Qty | - | | Qty | | Inspected |
| C # | omment | | <i>Units</i> Each | | Estimated | 1 | Qty | Actual | |
| C # 1 | omment Material / Labor | Description / Comment | | Qty | Estimated | 1 | Qty | Actual | |
| C # 1 | omment Material / Labor Insulation | Description / Comment DHW Pipe Insulation | Each | Qty 1 | Estimated | 1 | Qty | Actual | |
| C # 1 2 | omment Material / Labor Insulation Labor | Description / Comment DHW Pipe Insulation DHW Pipe Insulation | Each Each | Qty 1 | Estimated | 1 | Qty | Actual | |
| C # 1 2 | Material / Labor Insulation Labor Other | Description / Comment DHW Pipe Insulation DHW Pipe Insulation | Each Each | Qty 1 | Estimated | 1 | Qty | Actual | |
| C # 1 2 | Material / Labor Insulation Labor Other | Description / Comment DHW Pipe Insulation DHW Pipe Insulation | Each Each | Qty 1 | Estimated | 1 | Qty | Actual | |
| C # 1 2 | Material / Labor Insulation Labor Other | Description / Comment DHW Pipe Insulation DHW Pipe Insulation | Each Each | Qty 1 1 1 | Estimated | 1 | | Actual | |
| C # 1 2 | Material / Labor Insulation Labor Other | Description / Comment DHW Pipe Insulation DHW Pipe Insulation | Each Each | Qty 1 1 1 | Estimated Unit Cost | 1 | | Actual Unit Cost | |
| C # 1 2 | Material / Labor Insulation Labor Other | Description / Comment DHW Pipe Insulation DHW Pipe Insulation | Each Each | Qty 1 1 1 | Estimated Unit Cost | 1 | | Actual Unit Cost | |

| 1 | <i>Measure</i> 15 CO N | Monitor is Needed | | | Component | ts | | | Inspecte |
|--------------------|--|--|----------------------|----------------|---------------------|-------|-----|------------------|----------|
| C | omment | | | | | | | | |
| | | | | | Estimated | | | Actual | |
| # | Material / Labor | Description / Comment | Units | Qty | Unit Cost | Total | Qty | Unit Cost | Total |
| 1 | Health and Safety | CO monitor | Each | 1 | | | | | |
| 2 | Labor | Labor | Hour | 1 | | | | | |
| C | Other Detail | | | | | | _ | | |
| | | | | | | | | | |
| | | | | | | | | | |
| | | | | Measur | e Sub Total: | |] | Sub Total: | |
| | Measure 16 Insta | all Bathroom Exhaust F | an | | Componen | ts | | | Inspecte |
| | Measure 16 Insta | all Bathroom Exhaust F | - Fan | | Component | | | | Inspecte |
| C | omment | | | | Estimated | | Ofv | Actual | |
| C | | Description / Comment | Fan Units Each | Qty 1 | - | | Qty | | Inspecte |
| C :# | omment Material / Labor | Description / Comment | Units | Qty | Estimated | | Qty | Actual | |
| C # 1 | omment Material / Labor Health and Safety | Description / Comment Bathroom exhaust fan | <i>Units</i> Each | Qty 1 | Estimated | | Qty | Actual | |
| C # 1 | omment Material / Labor Health and Safety Labor | Description / Comment Bathroom exhaust fan | <i>Units</i> Each | Qty 1 | Estimated | | Qty | Actual | |
| C # 1 | omment Material / Labor Health and Safety Labor | Description / Comment Bathroom exhaust fan | <i>Units</i> Each | Qty 1 | Estimated | | Qty | Actual | |
| C # 1 | omment Material / Labor Health and Safety Labor | Description / Comment Bathroom exhaust fan | Units Each Hour | Qty 1 1 | Estimated | | | Actual | |
| C # 1 2 | omment Material / Labor Health and Safety Labor | Description / Comment Bathroom exhaust fan | Units Each Hour | Qty 1 1 | Estimated Unit Cost | | | Actual Unit Cost | |
| C # 1 2 | omment Material / Labor Health and Safety Labor Other Detail | Description / Comment Bathroom exhaust fan | Units Each Hour | Qty 1 1 | Estimated Unit Cost | | | Actual Unit Cost | |

| | Measure 17 Insta | III Kitchen Exhaust Fan | | | Componen | ts | | | Inspected |
|----------|---------------------------|-------------------------|-------|--------|---------------------|-------|-----|------------|-----------|
| • | | | | | Estimated | 1 | | Actual | |
| # | Material / Labor | Description / Comment | Units | Qty | Unit Cost | Total | Qty | Unit Cost | Total |
| 1 | Health and Safety | Kitchen exhaust fan | Each | 1 | | | | | |
| 2 | Labor | Labor | Hour | 1 | | | | | |
| 0 | ther Detail | | | | | | | | |
| | | | | | | | | | |
| | | | | Measur | e Sub Total: | | | Sub Total: | |
| | Measure 18 Smo Comment | ke Detector is Needed | | | Componen Estimated | | | Actual | Inspected |
| # | Material / Labor | Description / Comment | Units | Qty | Unit Cost | Total | Qty | Unit Cost | Total |
| 1 | Health and Safety | | Each | 1 | | | | | |
| 2 | Labor | Labor | Hour | 1 | | | | | |
| 0 | ther Detail | | | | | | 1 | | |
| | | | | | | | | | |
| | | | | | | | | | |
| | | | | Measur | e Sub Total: | | , | Sub Total: | |
| | Field Notes: | | | | | | | | |
| <u> </u> | | | | | | | | | |